

What's next with the IPS Rule change?

In the next few months we will be posting the proposed tables which will list out all of the current, and new, deficiencies and violations that are on the IPS report. We will be accepting pre public comment on these as well. Below are a few examples of some of the changes we are proposing.

<b>Deficiency Code</b>	<b>(CURRENT) Database Description</b>	<b>(CURRENT) Deficiency Type</b>	<b>(CURRENT) IPS</b>	<b>DRAFT Storage Tank Design and Construction</b>	<b>(PROPOSED) Deficiency Type</b>	<b>(PROPOSED) IPS Points</b>	<b>Rule Reference</b>
VL01	STORAGE STRUCTURE MISSING A PROPER OVERFLOW	SIG	15	Tank overflow is present	Sig	50	R309-545-13
M007	CCC-LACKS ON-GOING ENFORCEMENT PLAN	MIN	10	Water System has a cross connection control program that includes documentation of on-going enforcement activities	Min	5	R309-105-12(2)
SS04	SPRING BOX LACKS PROPER OVERFLOW/DRAIN LACKS PROPER SCREEN	Sig	5	Overflow and drain for junction and collection boxes screened with a #4 mesh screen	Sig	25	R309-515-7(7)(d)
SP06	NO PER FOR NEW ACTIVE SOURCE	SIG	150	All new sources have an approved PER	Sig	50	R309-600-13 & R309-605-9

Timeline for the IPS Rule change:

- September through November 2018 – Discuss, educate, get comments
- January through March 2019 – Share impact, show side by side IPS reports
- April through October 2019 – Rule change process (DW Board, official public comments)
- January 2020 – Implement new IPS Rule